Item	Condition	Notes
Agility Trail	Low	Rot to cross member of chain-walk.
Multi Component	Medium	
Multi Component	Medium	Frayed pull-rope/cable. Protruding base rail to cargo-net.
	Low	Timber anchorage rail for cargo-net loose.
	Low	Repair IAS around bottom of slide.
	Further	Protective caps needed to bolts/nuts.
	Investigation	·
Cradle Swings	ok	
Flat Seat Swings	ok	
Spring Bird Rocker	Medium	Rust to spring
Spring See-Saw	Medium	Rust to spring
Rocker		
Picnic Table	ok	
Playground bin	ok	
Playground Bench	ok	
Millennium Bench	ok	(By Church)
Queen's Bench	ok	(by Football goal)
Plank Bench	ok	
Basket Ball	ok	
Football Goal	ok	
Bin near gate	ok	
Fencing	Low	Base of entrance gate post rotten and getting worse.
Portakabin Stores	ok	(not EPC property) Minor Graffiti to stores.
Flag pole	ok	
Notice Board	ok	