

## Viper Play Area Inspection - Date: 23 June 2022

Item	Condition/Risk	Notes
Shelter	Low	Query unfixed benches?
Roller Track	ok	
Group Swing	ok	
Cableway	Low	Ground clearance under 65kg load approx. 250mm
Hamster Wheel	Low	Missing bolt to one panel.
Climber Block	Low	(Upper elements need inspection via ladder: Jan, April, July, Oct)
Carousel	Low	Ground clearance differs from BS EN 1176-5:2019
White Seat	ok	
Waste Bin Plastic	ok	
Waste Bin Metal	Low	Bin not fixed to base. Bin could be easily 'up-rooted' or pushed over. Top dented.
Surround fencing	ok	
VIPER signboard	ok	
Entrance Gates	ok	