

Viper Play Area Inspection - Date: 8-5-2024

Item	Condition/Risk	Notes
Shelter	Low	unfixed benches?
Roller Track	ok	
Group Swing	ok	
Cableway	ok	Ground clearance under 65kg load approx. 400mm-2 Nov 22, 380mm-4 Jan23, 375mm 12 Apr 23. Not checked June, <300mm July - Re-adjusted >400mm. Jan 24 – ok Feb 24 – ok. April - ok
Hamster Wheel	ok	Missing bolt to panel
Climber Block	ok	(Upper elements need inspection via ladder: Jan, April, July, Oct)
Carousel	Low	Ground clearance differs from BS EN 1176-5:2019
White Seat	ok	
Waste Bin Plastic	ok	
Waste Bin Metal	ok	Top dented.
Surround fencing	ok	
VIPER signboard	ok	
Entrance Gates	ok	

N.B. Brambles and nettles and hedge close to equipment