

Queen's Garden Inspection – Date: 31-7-24

Item	Condition/risk	Notes
Carousel	ok	
Multi Component	ok	
Cradle Swings	ok	
Flat Seat Swings	ok	
Spring Lion Rocker	ok	
Spring Frog Rocker	ok	
Picnic Table	ok	
Playground bin	ok	
Playground Bench	ok	
Millennium Bench	ok	(By Church)
Queen's Bench	ok	(by Football goal)
Plank Bench	ok	
Basket Ball	ok	Back panel missing
Football Goal	ok	
Samba Goal	ok	
Bin near gate	ok	
Fencing	ok	
Portakabin Stores	Low	(not EPC property) Timber step outside side entrance rotten
Flag pole	ok	
Notice Board	ok	