

Viper Play Area Inspection - Date: 28-8-2024

Item	Condition/Risk	Notes
Shelter	Low	unfixed benches?
Roller Track	ok	
Group Swing	ok	
Cableway	ok	Ground clearance under 65kg load approx. Re-set to 400mm 28-8-24
Hamster Wheel	ok	Missing bolt to panel
Climber Block	ok	(Upper elements need inspection via ladder: Jan, April, July, Oct)
Carousel	Low	Ground clearance differs from BS EN 1176-5:2019
White Seat	ok	
Waste Bin Plastic	ok	
Waste Bin Metal	ok	Top dented.
Surround fencing	ok	
VIPER signboard	ok	
Entrance Gates	ok	